
Pedestal Base

Tables



Hardware Included:

Tools Required:





• Extended allen wrench

(8) #12 x 1 Pan Head Screw



(2) 3/8"-16 X 1-1/4" FH SCREW

Step 1:

Place the table top upside down on a clean, padded surface.

Step 2:

Center leg assembly on underside of top and attach using #12 x 1" PH Screws (do not over tighten).

Step 3: Use an extended allen wrench for maxium torque when attaching disc base to column.

* NOTE:

Multiple leg bases attach the same as single leg bases.

