

Benches

General Specifications

Frame:
Frame is solid wood. All joints are double doweled, screwed and glued. Frames are reinforced with solid wood corner blocks under seat. Wood stretcher spans between each front and rear leg pair, and two solid wood stretchers span between each end frame at the top and one centered on the lower end frame calls. Frame is fitted with four Nickel tack glides.

Cushioned seat:


Interior seat construction consists of sheet webbing strectched and stapled securely to the seat frame. The seat is attached to the frame by four screws from the underside. The interior back construction consists of 2" thick polyprophylene webbing stretched and stapled to a 1/2" thick backer board.

Wood seat:

Interior seat construction consists of 1-3/8" thick solid wood made of glued up strips of wood no less than 1" or greater than 4" in width. Seat cushion is attached to bench frame via wood screws.

Finish:

See mediatechnologies® Finish and Color Guide for choices.



						Воо									k Bench
Model Number	Base	Seat	Seat Hgt.	Wgt. (lbs.)	COM Yd.	List Prices									
						All Wood	Grade 1 COM	Grade 2	Grade 3	Grade 4	Grade 5	Grade 6	Grade 7	Grade 8	Grade 9
BMB-1848A	Wood Post	Oak	18"	67	N/A	\$1,213	ALL WOOL)							
BMB-1848AM	Wood Post	Maple	18"	67	N/A	\$1,213	ALL WOOL	ALL WOOD							
BMB-1848C	Wood Post	Oak/Uph	18"	61	1 2/3	N/A	\$1,342	\$1,364	\$1,383	\$1,407	\$1,427	\$1,447	\$1,469	\$1,490	\$1,512
BMB-1848CM	Wood Post	Maple/Uph	18"	61	1 2/3	N/A	\$1,342	\$1,364	\$1,383	\$1,407	\$1,427	\$1,447	\$1,469	\$1,490	\$1,512
BMB-1860A	Wood Post	Oak	18"	75	N/A	\$1,446	ALL WOOD								
BMB-1860A	Wood Post	Maple	18"	75	N/A	\$1,446	ALL WOOD								
BMB-1860C	Wood Post	Oak/Uph	18"	68	2	N/A	\$1,484	\$1,519	\$1,554	\$1,590	\$1,625	\$1,659	\$1,696	\$1,735	\$1,771
BMB-1860CM	Wood Post	Maple/Uph	18"	68	2	N/A	\$1,484	\$1,519	\$1,554	\$1,590	\$1,625	\$1,659	\$1,696	\$1,735	\$1,771



Required to order:

- Model # including: wood selection
- · wood finish
- fabric selection if applicable

Prices listed above are for an oak construction. Seats constructed of maple or other materials may incur an upcharge