

Hardware Included:

Tools Required:

• #3 Phillips Head Screwdriver



#12 x 1 Pan Head Screw

Step 1:

Place the table top upside down on a clean, padded surface.

Step 2:

Center leg assembly on underside of top and attach using #12 x 1" PH Screws (do not over tighten).