Desks

General Specifications

Cabinet Base/Toe:

The inside front and side panels that comprise the base cabinet, including the toe, shall be $\ensuremath{\%"}$ particleboard core with 3mm banding on the bottom edge and .5mm banding on the exposed side edges. Panels are joined with glue and dowel construction. Panels shall be finished on both faces in high-pressure laminate or premium oak veneer (unless another species is specified). The cabinet base shall include a sub top of %" particle board core with 3mm banding on the user edge.

Decorative Overlay Panels:

Decorative front and side overlay panels are 34" particleboard core with .050" high-pressure laminate or sequenced premium oak veneer faces (unless another species is specified) with .5mm banding. Top overlay panel is 2-7/8" O.A. height. Middle overlay panel is 16-7/17" O.A. height. Lower overlay panel is 2-7/8" O.A. height.

Worksurface:


The worksurface shall be 1-1/8" particleboard core with .050" high-pressure laminate and .030" phenolic backer surfaces. The worksurface shall receive 1/4" wood banding.




Main Unit Left

	Wood - Main Desk Unit - Left		
Part Number	Item Description	Wgt.	List Price
DMDL-E3084-29	30" x 84" x 29"H/42"H	420	\$17,358
DMDL-E3096-29	30" x 96" x 29"H/42"H	466	\$17,358
DMDL-E30120-29	30" x 120" x 29"H/42"H	560	\$20,474

Transaction Top worksurface is 1-1/8" particleboard core with .050" highpressure laminate faces and 1/4" wood banding. Transaction top supports are 3/4" particleboard core with .050" high-pressure laminate faces and 3mm banding. Transaction top front and side faces are 3/4" particleboard core with .050" highpressure laminate or premium oak veneer (unless another species is specified) with 3mm banding. There is a mitered joint between front and side faces. (Transaction top is typically not included in construction of returns).







Main Unit Left

	Laminate - Main Desk Unit - Lef		
Part Number	Item Description	Wgt.	List Price
DMDL-C3084L-29	30" x 84" x 29"H/42"H	420	\$14,984
DMDL-C3096L-29	30" x 96" x 29"H/42"H	466	\$14,984
DMDL-C30120L-29	30" x 120" x 29"H/42"H	560	\$16,978



Main Unit Right

	Wood - Main Desk Unit -Right		
Part Number	Item Description	Wgt.	List Price
DMDR-E3084-29	30" x 84" x 29"H/42"H	420	\$17,358
DMDR-E3096-29	30" x 96" x 29"H/42"H	466	\$17,358
DMDR-E30120-29	30" x 120" x 29"H/42"H	560	\$20,474



Main Unit Right

	Laminate - Mai	n Desk	Unit -Right
Part Number	Item Description	Wgt.	List Price
DMDR-C3084L-29	30" x 84" x 29"H/42"H	420	\$14,984
DMDR-C3096L-29	30" x 96" x 29"H/42"H	566	\$14,984
DMDR-C30120L-29	30" x 120" x 29"H/42"H	560	\$16,978



Return Unit Left

	Wood - De	sk Return	Unit -Left
Part Number	Item Description	Wat.	List Price
DMRL-E3036-29	30" x 36" x 29"H	148	\$2,497
DMRL-E3042-29	30" x 42" x 29"H	166	\$2,852
DMRL-E3048-29	30" x 48" x 29"H	184	\$2,852



Return Unit Left

	Laminate -	Desk Return	Unit -Left
Part Number	Item Description	Wgt.	List Price
DMRL-C3036L-29	30" x 36" x 29"H	148	\$2,058
DMRL-C3042L-29	30" x 42" x 29"H	166	\$2,354
DMRL-C3048L-29	30" x 48" x 29"H	184	\$2,354



Return Unit Right

	Wood - Desk Return Unit -Right		
Part Number	Item Description	Wgt.	List Price
DMRR-E3036-29	30" x 36" x 29"H	148	\$2,497
DMRR-E3042-29	30" x 42" x 29"H	166	\$2,852
DMRR-E3048-29	30" x 48" x 29"H	184	\$2.852



Return Unit Right

	Laminate - De	sk Return l	Jnit -Right
Part Number	Item Description	Wgt.	List Price
DMRR-C3036L-29	30" x 36" x 29"H	148	\$2,058
DMRR-C3042L-29	30" x 42" x 29"H	166	\$2,354
DMRR-C3048L-29	30" x 48" x 29"H	184	\$2,354



Laminate (HPL) - Pedestal Hanging File/File			
Model Number	Description	Wgt.	List Price
WHPS612218-W-LL	14.8125"W x 18"D x 20"H	54	\$743

Required to order: Model # including options if applicable.

- HPL selection(s)
- · veneer selection and finish (if applicable).

Note: Veneer pricing shown is for oak veneer. Use of maple or other species may incur an upcharge.

Designations Right and Left are determined from the perspective of the desk user.

Please note that Domino Desk image on page 108 of the Anyspace Catalog is identified incorrectly. The correct model number should be DMDL-3096-29.

Prices and specifications subject to change without notice

P-DOMINO-220601